

# T.F. GREEN AIRPORT (PVD) FIELD CONDITION REPORT

OFFICE: (401) 691-2265 24 HR: (401) 447-6893

DATE: 6/24/2018

TIME: 16:04

INSPECTED BY: DEVON DUNPHY

UPDATED BY: DEVON DUNPHY

---

## WEATHER RELATED UPDATES

---

## SURFACE CONDITIONS

---

ALL SURFACES DRY

---

## BRAKING ACTION / RwyCC VALUES

<u>RUNWAY</u>	<u>TIME</u>	<u>TOUCHDOWN</u>	<u>MIDPOINT</u>	<u>ROLLOUT</u>
---------------	-------------	------------------	-----------------	----------------

---

TAXIWAY AND APRON BRAKING ACTION : TAXIWAYS:

APRONS:

---

## AIRFIELD REMARKS

<u>SURFACES</u>	<u>STATUS</u>	<u>REMARKS</u>
RUNWAY 5-23		RWY 5/23: TWY LEAD OFF CL MARKINGS OBSC BY RUBBER RWY 23: FIXED DIST AND TDZ MARKINGS NON STD
RUNWAY 16-34		RWY 34: LOCATION SIGN NON STD [MISSING] LEFT SIDE RWY 34: RWY 5/23 HOLDING POSITION SIGN, R SIDE NOT LGTD
TAXIWAY A		
TAXIWAY B		
TAXIWAY C		
TAXIWAY C1		
TAXIWAY E		
TAXIWAY F		
TAXIWAY M		
TAXIWAY M1		
TAXIWAY M2		
TAXIWAY N		EDGE LINE NON-STD [REMOVED] BTN TWY F AND RWY 16/34 NE SIDE
TAXIWAY S		
TAXIWAY T	CLOSED	BTN TWY V AND S END OF TERMINAL RAMP RUN-UP PAD CLSD
TAXIWAY V		
NORTHEAST RAMP		
NORTHWEST RAMP		
TERMINAL RAMP		

---

## MISCELLANEOUS AERODROME REMARKS

GENERAL TAXIWAYS: NUMEROUS NON-STANDARD EDGE MARKINGS DUE TO PAINT REMOVAL AND CRACK SEAL