

**T.F. GREEN AIRPORT (PVD)
FIELD CONDITION REPORT**

OFFICE: (401) 691-2265 24 HR: (401) 447-6893

DATE: 4/22/2018

TIME: 4:02

INSPECTED BY: KYLE MCKENNA

UPDATED BY: KYLE MCKENNA

WEATHER RELATED UPDATES

SURFACE CONDITIONS

ALL SURFACES DRY

BRAKING ACTION / RwyCC VALUES

RUNWAY TIME TOUCHDOWN MIDPOINT ROLLOUT

TAXIWAY AND APRON BRAKING ACTION : TAXIWAYS: APRONS:

AIRFIELD REMARKS

<u>SURFACES</u>	<u>STATUS</u>	<u>REMARKS</u>
RUNWAY 5-23		RWY 23: NOT STD THR, FIXED DIST AND TDZ MARKINGS
RUNWAY 16-34		RWY 34: LOCATION SIGN BTN RWY 05/23 AND TWY M, LEFT SIDE NON-STD

TAXIWAY A		
TAXIWAY B		
TAXIWAY C		
TAXIWAY C1		
TAXIWAY E		
TAXIWAY F		
TAXIWAY M		
TAXIWAY M1		
TAXIWAY M2		
TAXIWAY N		NON-STD EDGE LINE [REMOVED] BTN TWY F AND RWY 16/34, NE SIDE
TAXIWAY S		
TAXIWAY T	CLOSED	BTN TWY V AND TERMINAL RAMP RUN UP PAD CLSD
TAXIWAY V	CLOSED	BTN TWY C AND RWY 16/34 TWY CL LGTS OTS N OF RWY 16/34
NORTHEAST RAMP		
NORTHWEST RAMP		
TERMINAL RAMP		

MISCELLANEOUS AERODROME REMARKS

GENERAL TAXIWAYS: NUMEROUS NON-STANDARD AND OBSCURED CL AND EDGE MARKINGS DUE TO PAINT REMOVAL AND CRACK SEAL